

| | |
|--------------------|---|
| Application | HVAC |
| Problem | The original fan was showing signs of failure, as cracks and fissures began to appear around the hub. |
| Solution | Before failure occurred, SPX Cooling Technologies expedited a Marley X7 fan to replace the original fan, preventing mechanical and structural damage. |
| Results | The customer's tower was returned to operating order. |



Photo courtesy of Bob Stortz, Midwest Machinery

Contact your Marley representative to identify parts for other manufacturers' towers: spxcooling.com/replocator

SPX COOLING TECHNOLOGIES, INC.

7401 WEST 129 STREET
OVERLAND PARK, KS 66213 USA
913 664 7400 | spxcooling@spx.com
spxcooling.com

CCS-X7-18 | ISSUED 09/2018

COPYRIGHT © 2018 SPX Cooling Technologies Inc. All rights reserved.

In the interest of technological progress, all products are subject to design and/or material change without notice.

