

Application	HVAC
Problem	The customer's cooling tower is a brand that no longer exists, making parts replacement and service more challenging. The cooling tower fan was the most immediate issue. Sourcing obsolete components and identifying alternatives can be time-consuming and often futile. As parts continued to wear and fatigue, operators were concerned about extending the tower's lifecycle.
Solution	The Marley X7 Fan was identified as a high-performing solution. SPX Cooling Technologies customized the length of the fan shaft so fit and installation were seamless. Marley MC120S™ Fill, drift eliminators and a custom-designed outlet for piping were also specified and installed.
Results	New, more efficient components returned the cooling tower to operation and effectively extended its lifecycle.



Photo courtesy of Dreher & Associates

Contact your Marley representative to identify parts for other manufacturers' towers: spxcooling.com/relocator

SPX COOLING TECHNOLOGIES, INC.

7401 WEST 129 STREET
 OVERLAND PARK, KS 66213 USA
 913 664 7400 | spxcooling@spx.com
spxcooling.com

CCS-X7-19 | ISSUED 01/2019
 COPYRIGHT © 2019 SPX Cooling Technologies Inc. All rights reserved.
 In the interest of technological progress, all products are subject to design and/or material change without notice.

